



TRIMBLE BD930 UPDATE

PRODUCT END OF LIFE / END OF MANUFACTURING ANNOUNCEMENT

Date: May 21, 2019

Trimble® Integrated Technologies announces this product bulletin to inform our customers of planned product migration activities surrounding our BD930 product as follows:

- ▶ The BD930 is now officially in its end of life / end of manufacturing phase.
- ▶ Trimble® does not encourage development of any new projects using the BD930.
- ▶ Trimble® cannot guarantee product supply after Q2 2019.
- ▶ Trimble® suggests BD930 customers looking for a replacement product should connect with their sales contact to determine the best fit for a replacement product.
 - ▶ Email: sales-intech@trimble.com

The following part numbers will be affected:

| Product | Part Number(s) | Description |
|---------------|----------------|--|
| Trimble BD930 | 60930-01 | Trimble BD930 , All options disabled, requires upgrade to output positions |
| | 60930-03 | Trimble BD930, GPS, L1 Autonomous/SBAS, 20Hz |
| | 60930-04 | Trimble BD930, GPS, L1 DGPS Base/Rover, 5Hz |
| | 60930-05 | Trimble BD930, GPS, L1 DGPS Base/Rover, 20Hz |
| | 60930-07 | Trimble BD930, GPS, L1 DGPS Rover, 20Hz |
| | 60930-08 | Trimble BD930, GPS, L1 RTK Base/Rover, 5Hz |
| | 60930-09 | Trimble BD930, GPS, L1 RTK Base/Rover, 20Hz |
| | 60930-12 | Trimble BD930, GPS, L1/L2/L5 RTK Base/Rover, 5Hz |
| | 60930-13 | Trimble BD930, GPS, L1/L2/L5 RTK Base/Rover, 20Hz |
| | 60930-14 | Trimble BD930, GPS, L1/L2/L5 RTK Rover, 5Hz |
| | 60930-15 | Trimble BD930, GPS, L1/L2/L5 RTK Rover, 20Hz |
| | 60930-23 | Trimble BD930, GPS, GLN, L1 Autonomous/SBAS, 20Hz |
| | 60930-24 | Trimble BD930, GPS, GLN, L1 DGPS Base/Rover, 5Hz |
| | 60930-25 | Trimble BD930, GPS, GLN, L1 DGPS Base/Rover, 20Hz |
| | 60930-27 | Trimble BD930, GPS, GLN, L1 DGPS Rover, 20Hz |
| | 60930-28 | Trimble BD930, GPS, GLN, L1 RTK Base/Rover, 5Hz |
| | 60930-29 | Trimble BD930, GPS, GLN, L1 RTK Base/Rover, 20Hz |
| | 60930-32 | Trimble BD930, GPS, GLN, L1/L2/L5 RTK Base/Rover, 5Hz |
| | 60930-33 | Trimble BD930, GPS, GLN, L1/L2/L5 RTK Base/Rover, 20Hz |
| | 60930-34 | Trimble BD930, GPS, GLN, L1/L2/L5 RTK Rover, 5Hz |
| | 60930-35 | Trimble BD930, GPS, GLN, L1/L2/L5 RTK Rover, 20Hz |
| | 60930-56 | Trimble BD930, GPS, GLN, BDS L1 Autonomous/SBAS, 20Hz |
| | 60930-57 | Trimble BD930, GPS, GLN, BDS L1, DGPS Base/Rover, 20Hz |
| | 60930-58 | Trimble BD930, GPS, GLN, BDS, L1/L2/L5 RTK Base/Rover, 5Hz |



| Product | Part Number(s) | Description |
|---------------|----------------|---|
| Trimble BD930 | 60930-59 | Trimble BD930, GPS, GLN, BDS L1/L2/L5 RTK Base/Rover, 20Hz |
| | 60930-63 | Trimble BD930, GPS, GLN, GAL, BDS L1 Autonomous/SBAS, 20Hz |
| | 60930-64 | Trimble BD930, GPS, GLN, GAL, BDS L1, DGPS Base/Rover, 5Hz |
| | 60930-65 | Trimble BD930, GPS, GLN, GAL, BDS L1, DGPS Base/Rover, 20Hz |
| | 60930-68 | Trimble BD930, GPS, GLN, GAL, BDS L1, RTK Base/Rover, 5Hz |
| | 60930-69 | Trimble BD930, GPS, GLN, GAL, BDS L1, RTK Base/Rover, 20Hz |
| | 60930-77 | Trimble BD930, GPS, GLN, GAL, BDS L1/L2/L5 RTK Base/Rover, 20Hz |
| | 60930-83 | Trimble BD930, GPS, BDS, L1 Autonomous/SBAS, 20Hz |
| | 60930-85 | Trimble BD930, GPS, BDS, L1 DGPS Base/Rover, 20Hz |
| | 60930-88 | Trimble BD930, GPS, BDS, L1/L2/L5 RTK Base/Rover, 5Hz |
| | 60930-89 | Trimble BD930, GPS, BDS, L1/L2/L5 RTK Base/Rover, 20Hz |
| | 60930-90 | Trimble BD930, GPS, GLN, GAL, BDS L1/L2/L5, Heading Only Rover |
| | 96062-00 | Trimble BD910/BD920/BD930 Evaluation Kit |
| | 95730-01 | Trimble BD930 Field Upgrade |

Parts, Servicing and Warranty Information

The standard Trimble policy for parts, servicing and warranty applies.

Availability

The above mentioned products will be available while supplies last.

